

Repeated Ceramic Head Fracture after Ceramic-on-ceramic Total Hip Arthroplasty

Myung-Sik Park, MD, Sun-Jung Yoon, MD, Myung-Jae Yoo, MD

Department of Orthopedic Surgery, Research Institute of Clinical Medicine,
Chonbuk National University Hospital, Jeonju, Korea

Alumina ceramic-on-ceramic total hip arthroplasty is a widely-adopted option, especially for younger patients, due to low wear, scratch resistance, the wettable characteristics of alumina ceramics, and because of the relatively low biological reactivities of ceramic wear particles. However, fracture remains a significant problem because ceramics are inherently brittle, and few reports have been issued on short head fractures. In the described case, a ceramic head fracture occurred only 8 months after replacing the original head and with a new 28 mm head and liner. Both of these incidents may have been caused by head-to-liner impingement due to excessive anteversion of the metal shell. During the second revision surgery, this situation was managed successfully using a conventional elevated-polyethylene liner and a CoCr metal head, while retaining all metal implants.

Key Words: Total hip arthroplasty, Ceramic-ceramic total hip arthroplasty, Ceramic head fracture

Introduction

Early generation ceramic articulations were problematic in terms of ceramic implant fracture and wear¹⁻³. Although the mechanical properties of ceramic material have improved during the last three decades, ceramic component fracture remains an issue⁴. Many authors have reported fractures of the ceramic head⁵⁻⁸, and a few have described ceramic acetabular insert fracture⁹⁻¹¹. However, these complications are only encountered rarely, and all cases reported to date involve a history of minor

trauma. Here, we describe a case that required 2nd-revision with a CoCr metal head and conventional polyethylene liner due to a recurrent fracture of the ceramic head.

Case report

In August 2006, a 44-year-old man (height 180 cm and weight 70 kg) visited our emergency room due to a pain in his left hip. He had not experienced unusual impact or trauma. Previously, he had undergone bilateral primary THA due to avascular necrosis at other university hospital during 2001. The implant used was composed of a hemispherical titanium metal shell and the femoral component was a slightly tapered, rectangular, collarless titanium stem. The proximal one-third of the stem was coated with plasmapore (BiContact, Aesculap, Tuttlingen, Germany), and the articulating component was composed of a ceramic liner and a 28 mm short ceramic head (BioloX Forte, Ceramtec, Plochingen, Germany). Although the femoral stem and acetabular cup were well fixed by bony ingrowths, a ceramic

Submitted: October 5, 2011

1st revision: December 2, 2011

2nd revision: February 10, 2012

3rd revision: February 13, 2012

4th revision: March 12, 2012

5th revision: March 14, 2012

Final acceptance: March 20, 2012

• Address reprint request to **Myung-Sik Park, MD**

Department of Orthopedic Surgery, Research Institute of
Clinical Medicine, Chonbuk National University Hospital,
Jeonju 561-712, Korea

TEL: +82-63-250-1768 FAX: +82-63-271-6538

E-mail: mspark@jbnu.ac.kr

Copyright © 2012 by Korean Hip Society

fracture was observed on the left side of the ceramic head (Fig. 1). Computed tomography showed an intact liner and broken femoral head in the liner (Fig. 2). Intraoperatively, we observed that the trunion of the femoral stem was not grossly damaged at revision surgery and had a near normal contour. We removed ceramic particular debris carefully and exchanged the head and liner with and a new liner and 28 mm medium neck because of provide stability to the surrounding muscles. The patient followed an uneventful postoperative course (Fig. 3).

However, eight months later, he revisited our emergency room because he felt a 'crunching' sensation in the left hip while walking. Again, he had not experienced any unusual impact or trauma. In

the emergency room, we took radiographs of both hips (Fig. 4A). The stem and acetabular cup were still well fixed, but the left side of the ceramic head was fractured and dislocated. Computerized tomographic (CT) scans of both hips revealed metal shells with a normal abduction angle range of 46.14° , but anteversion of the left metal shell was found to be 36.09° (Fig. 4B).

The patient underwent a second revision surgery. Multifragmentary fractured particles of the ceramic head (one on the apical segment and four on the lateral segment) and dark metallic stains were observed on the medial surface of the fractured head. This stain was revealed Ti particles on EDAX study. At the peripheral rim of the ceramic liner, a similar metallic stain and chip fractures were found (Fig. 5A). Interestingly, a groove was observed around the lateral and posterior neck base of the femoral stem (Fig. 5B), indicating impingement between the stem neck and the ceramic liner. During second revision surgery, the fractured ceramic head and the ceramic liner were replaced with 28 mm CoCr medium neck and an elevated-polyethylene liner, which were both replaced anterosuperiorly instead of posteriorly, to overcome excessive anteversion (Fig. 6). The trunion of the femoral stem was retained, although a portion of it was scratched and grooved, because the femoral stem showed bony ingrowth stabilization. Two years after second revision, no postoperative complication or dislocation had occurred, and he was working



Fig. 1. Ceramic head fracture in the left hip.




Fig. 2. Computed tomograph showing ceramic head fracture fragments were retained by the metal shell.



successfully as a farmer.

Discussion

Alumina ceramic-on-ceramic bearings have been used clinically for more than 20 years⁶⁾. During these two decades, the mechanical properties of ceramic materials have been improved by hot isocratic pressing, laser marking, and nondestructive proof-testing¹²⁾. Yet, the risk of fracture remains a major, though fortunately, an uncommon problem. Recently, the majority of reported fractures associated with contemporary third-generation ceramic materials have been chip fractures of ceramic liners^{13,14)}, or ceramic liner fractures associated with the use of a sandwich-type acetabular component¹⁵⁾.

Patient-specific risk factors that contribute to ceramic component fractures include age, activity level, and a history of trauma^{10,11)}. Ha et al.¹⁰⁾ attributed ceramic liner fractures in Asian populations to activities, such as, as squatting, kneeling, and



Fig. 3. A new ceramic head and liner were inserted.




Fig. 4. (A) Second fracture of the ceramic head with dislocation and (B) cross sectional computed tomograph showing excessive anteversion of the metal shell and femoral stem.




Fig. 5. (A) A rim fracture and metal staining of the ceramic liner and multiple fragments of the ceramic head and (B) a deep groove (white arrow) was observed on the lateral base of the femoral stem.

sitting cross-legged, which can result in impingement and liner fracture. Our patient was Korean, relatively young, and had no trauma history, but presumably was more active than typical THA recipients.

In terms of operation-associated factors, Barrack et al.¹⁾ showed that optimal component positioning is crucial when ceramic-on-ceramic components are used. These components should be placed at less than 45° abduction and 10-15° anteversion on the acetabular side to optimize the distribution of forces over the surfaces of the femoral head and cup^{1,9,11,16)}. In our case, abduction and anteversion angles were 46.14° and 36.09°, respectively (Fig. 4). The presumptive cause of the refracture was positioning of the cup in excessive anteversion, which caused impingement between the posterior aspect of the stem neck and the liner followed by subluxation of the head, and head to liner impact due to reduction.

Other possible causative factors of alumina ceramic head fractures include; component design, the material properties of ceramic components, and manufacturing defects, such as, cone-trunion mismatch and ceramic deterioration¹⁷⁻²⁰⁾. The ceramic head to trunion taper contact area is an important aspect of component design, and importantly, a different neck length affects the head-trunion interface. Koo et al.²¹⁾ showed that fractures involved the thinnest circumferential portions of short necks




Fig. 6. New polyethylene liner and metal head were fitted to retained metal shell and the existing femoral component and small pieces of particles can be seen at posterosuperior capsule.

adjacent to the proximal edge of bore portion of the head, and that several vertical cracks extended from circular cracks to the lower edge of the short neck component. We postulate that the cause of the second ceramic head fracture in our case was not the use of short neck at first revision, but excessive anteversion of metal shell. These recurrent fracture can pose the main cause is the impingement of the metal liner and the base of the neck due to over anteversion of the metal shell followed by ceramic head to liner impact. This postulation is based on the presence of a deep groove in the lateral neck base and a ceramic liner rim fracture. And excessive anteversion of the metal shell on CT scan. On both occasions in our patient, fractures were not associated with trauma and fractures had a brittle fracture pattern. The patient received a 28 mm short neck ceramic head at primary surgery and medium neck at first revision.

Retrieved ceramic femoral heads have shown that metal staining, which appears as dark marks on the inner inferior surfaces of ceramic liners²²⁻²⁴⁾, is caused by metal transfer to the ceramic surface when a head contacts a metal shell during, for example, femoral head reduction or femoral head dislocation¹¹⁾. In our case, metallic staining was observed on the articular surfaces and lips of the ceramic liner, and multiple scratches were the observed on the taper of neck of the retained femoral stem (Fig. 5). Furthermore, EDAX showed that the metal staining on the liner rim was caused by Ti-alloy.

Several options are available for correcting a malpositioned metal shell and a femoral stem with a damaged taper by new implantation of the metal shell and femoral stem with large head or isolated revision on metal shell. We decided to retain all metal components because stable bony ingrowth of the metal shell and femoral component were evident, and thus, we replaced the articular portion only. We choose an elevated polyethylene liner and metal head combination to overcome the damaged taper and to compensate for anteversion of the metal cup. In the present case, during revision, to reduce excessive anteversion, the elevated rim of the polyethylene liner was replaced anterosuperiorly to compensate excessive anteversion and to use 28 mm CoCr metal head on the damaged trunion. After two

years of follow up post second revision, our patient was working as a farmer with polyethylene liner and metal head combination THA. However, we cannot conclude that metal shell and femoral stem retentions are optimal in cases of ceramic head fracture. Further studies with longer follow-ups are needed.

Nonetheless, we believe that ceramic-on-ceramic bearings are a good choice for primary THA, especially in young patients. When a hard bearing component as a ceramic head and ceramic liner is used, surgeons should ensure ranges of anteversion and inclination of the metal shell and anteversion of the femoral stem are acceptable.

REFERENCES

- Barrack, RL, Burak, C, Skinner, HB. *Concerns about ceramics in THA. Clin Orthop Relat Res.* 2004;429:73-9.
- Bierbaum BE, Nairus J, Kuesis D, Morrison JC, Ward D. *Ceramic-on-ceramic bearings in total hip arthroplasty. Clin Orthop Relat Res.* 2002;405:158-63.
- Sedel L. *Evolution of alumina-on-alumina implants: a review. Clin Orthop Relat Res.* 2000;379:48-54.
- Hannouche D, Nich C, Bizot P, Meunier A, Nizard R, Sedel L. *Fractures of ceramic bearings: history and present status. Clin Orthop Relat Res.* 2003;417:19-26.
- Arenas A, Tejero A, Garbayo A, Arias C, Barbadillo J, Lecumberri J. *Ceramic femoral head fractures in total hip replacement. Int Orthop.* 1999;23:351-2.
- Murphy SB, Ecker TM, Tannast M. *Two- to 9-year clinical results of alumina ceramic-on-ceramic THA. Clin Orthop Relat Res.* 2006;453:97-102.
- Pulliam IT, Trousdale RT. *Fracture of a ceramic femoral head after a revision operation. A case report. J Bone Joint Surg Am.* 1997;79:118-21.
- Torán MM, Cuenca J, Martínez AA, Herrera A, Thomas JV. *Fracture of a ceramic femoral head after ceramic-on-ceramic total hip arthroplasty. J Arthroplasty.* 2006;21:1072-3.
- Diwanji SR, Seon JK, Song EK, Yoon TR. *Fracture of the ABC ceramic liner: a report of three cases. Clin Orthop Relat Res.* 2007;464:242-6.
- Ha YC, Kim SY, Kim HJ, Yoo JJ, Koo KH. *Ceramic liner fracture after cementless alumina-on-alumina total hip arthroplasty. Clin Orthop Relat Res.* 2007;458:106-10.
- Hasegawa M, Sudo A, Uchida A. *Alumina ceramic-on-ceramic total hip replacement with a layered acetabular component. J Bone Joint Surg Br.* 2006;88: 877-82.
- Skinner HB. *Ceramic bearing surfaces. Clin Orthop Relat Res.* 1999;369:83-91.
- D'Antonio J, Capello W, Manley M, Bierbaum B. *New experience with alumina-on-alumina ceramic bearings for total hip arthroplasty. J Arthroplasty.* 2002;17:390-7.
- Garino JP. *Modern ceramic-on-ceramic total hip systems in the United States: early results. Clin Orthop Relat Res.* 2000;379:41-7.
- Park YS, Hwang SK, Choy WS, Kim YS, Moon YW, Lim SJ. *Ceramic failure after total hip arthroplasty with an alumina-on-alumina bearing. J Bone Joint Surg Am.* 2006;88:780-7.
- Hasegawa M, Sudo A, Hirata H, Uchida A. *Ceramic acetabular liner fracture in total hip arthroplasty with a ceramic sandwich cup. J Arthroplasty.* 2003;18:658-61.
- Callaway GH, Flynn W, Ranawat CS, Sculco TP. *Fracture of the femoral head after ceramic-on-polyethylene total hip arthroplasty. J Arthroplasty* 1995;10:855-9.
- Maccauro G, Piconi C, Burger W, et al. *Fracture of a Y-TZP ceramic femoral head. Analysis of a fault. J Bone Joint Surg Br.* 2004;86:1192-6.
- Masonis JL, Bourne RB, Ries MD, McCalden RW, Salehi A, Kelman DC. *Zirconia femoral head fractures: a clinical and retrieval analysis. J Arthroplasty.* 2004;19: 898-905.
- Willmann G. *Ceramic femoral head retrieval data. Clin Orthop Relat Res.* 2000;379:22-8.
- Koo KH, Ha YC, Jung WH, Kim SR, Yoo JJ, Kim HJ. *Isolated fracture of the ceramic head after third-generation alumina-on-alumina total hip arthroplasty. J Bone Joint Surg Am.* 2008;90:329-36.
- Kim YH, Ritchie A, Hardaker C. *Surface roughness of ceramic femoral heads after in vivo transfer of metal: correlation to polyethylene wear. J Bone Joint Surg Am.* 2005;87:577-82.
- Luchetti WT, Copley LA, Vresilovic EJ, Black J, Steinberg ME. *Drain entrapment and titanium to ceramic head deposition: two unique complications following closed reduction of a dislocated total hip arthroplasty. J Arthroplasty.* 1998;13:713-7.
- Yoo JJ, Kim HJ, Kim YM. *Damage of an alumina-on-alumina bearing surface from a difficult reduction of a total hip arthroplasty. A report of three cases. J Bone Joint Surg Am.* 2004; 86-A:376-8.

세라믹-세라믹 인공 고관절 치환술에서 반복된 세라믹 골두 골절

박명식 · 윤선중 · 유명재

전북대학병원, 임상의학연구소, 정형외과교실

인공 고관절 전치환 술에서 세라믹 비구 라이너와 세라믹 인공골두 조합 인공 고관절 전 치환술은 금속-금속 인공 고관절과 함께 내구성으로 인해 광범위하게 사용 되어지고 있다 세라믹-세라믹 조합형의 인공 고관절은 특히 젊은 환자에서 낮은 마모율, 닳아짐이 적고 친수성의 특성과 닳아진 마모편도 인체에 무해한 것으로 보고되고 있다. 반면 세라믹 골두의 골절은 커다란 단점이다. 보고는 적으나, 세라믹 골두의 단경부 형(short neck) 에서 많이 골절이 되고 있다. 본 증례는 두 차례의 골절로 단경부 형, 중간부 형(medium neck) 모두에서 골절이 되어 세라믹 문제뿐 아니라, 비구 컵의 비정상 위치에 의한 충돌로 인한 골절로 추정 되었다. 또한 치료법으로 철저한 활액막 제거 후 탈구 방지형 폴리아이너 비구 컵과 금속 대퇴골두로서 치료 하였으며 걱정되는 세라믹 마모 편에 의한 폴리아이너의 과도한 마모도 발생되지 않아 이를 보고 하고자 한다.

색인단어: 인공고관절 전치환술, 세라믹-세라믹 인공 고관절, 세라믹 골두 골절